

“HP01-TS setup.exe” software history 1.06

Here are reported only the last releases, the complete release history is available on request

| Ver. | Date | Applied Modifications |
|------|------------|--|
| 1.06 | 11/05/2022 | – New Narda Logo |
| 1.05 | 18/09/2017 | – New HP01-TS.exe release 1.05 – New HP01Up.exe release 1.03 – New firmware release 1.14 |
| 1.03 | 10/01/2017 | – New HP01-TS.exe release 1.03 |
| 1.02 | 24/11/2016 | – New HP01-TS.exe release 1.02 |
| 1.00 | 23/09/2016 | – New HP01-TS.exe release 1.00 |

| HP01-TS.exe | | |
|-------------|------------|---|
| Ver. | Date | Applied Modifications |
| 1.06 | 11/05/2022 | – New Narda Logo – Updated the support email shown under contacts submenu |
| 1.05 | 18/09/2017 | – Add FIR mode – Numeric/plot mode: improved report – Spectrum mode: add report – Various improvements requested by the market. |
| 1.03 | 10/01/2017 | – Improved management on the number of sweep in the waterfall and spectrogram mode |
| 1.02 | 23/11/2016 | – Every mode: <ul style="list-style-type: none"> ○ Improved resolution ○ Improved average up to 64 ○ Implemented Max Hold ○ Add check and warn in case a firmware upgrade is necessary – Numeric mode: <ul style="list-style-type: none"> ○ improved minimum band resolution ○ In the creation file “Measure.txt”, quantity set up on “mT” and multiplication factor 1000 with answer from the probe into “T” – Spectrum mode: <ul style="list-style-type: none"> ○ Modified set up management for span and range ○ Differentiated representation limits – Plot mode: <ul style="list-style-type: none"> ○ Add “Over Range” label – Spectrum/spectrogram/waterfall mode: <ul style="list-style-type: none"> ○ Modified wideband calculation ○ Add OLD/RUN button to stop and start a continuous sweep ○ Spectrogram reshaping ○ Fixed bug relative to a software closing with active markers |

| | | |
|------|------------|-----------------|
| 1.00 | 23/09/2016 | – First release |
|------|------------|-----------------|

| HP01Up.exe | | |
|-------------------|-------------|--|
| Ver. | Date | Applied Modifications |
| 1.03 | 17/08/2017 | – Software modification: the firmware is now saved in a public folder available to every users |
| 1.00 | 23/11/2016 | – First release |

| HP01 Firmware.exe | | |
|--------------------------|-------------|---|
| Ver. | Date | Applied Modifications |
| 1.14 | 07/07/2017 | <ul style="list-style-type: none"> – Introduced DCE mode (output filter 3dB@1Hz. Doubled initial auto off-timeout (2 minutes s) – Changed connection to 8053 (button first 5 seconds) |
| 1.06 | 22/11/2016 | <ul style="list-style-type: none"> – Wide-band and power Channel, resolution increased and various improvements – Regulation voltage levels |