

**L3HARRIS****narda** 
Safety Test Solutions

“NardaAMInstaller Setup.exe” software history

1.7

Ver.	Date	Applied Modifications
1.7	24/09/2021	– Setup version 1.34
1.6	26/08/2021	– Setup version 1.33
1.5	01/03/2021	– Setup version 1.32
1.04	18/05/2020	– Setup release 1.04
1.03	03/07/2019	– Setup release 1.03
1.01	05/11/2018	– First setup release 1.01 – NardaAMConfigurator.exe release 1.0.1

NardaAMConfigurator.exe		
Ver.	Date	Applied Modifications
1.34	24/09/2021	– Updated firmware for 8059 (Ver.2.15) – Solved issue, where the previous installation of NardaAMInstaller (1.33), would upload the wrong firmware version to the 8061 during the updating process
1.33	26/08/2021	– Updated firmware for 8061(Ver.1.43) – Under “Help” in the welcome screen , added link to a video tutorial on NardaAMInstaller. – Solved issue, where previous installation of NardaAMInstaller, weren't removed from windows installed software list.
1.31	18/05/2020	– Changed logo and information from the old Narda to the new brand L3Harris Narda – Fixed the SIM block in case the PUK code is requested before the PIN code
1.30	21/06/2019	– Added firmware update management – Improved WiFi management – Added management of all 8059 and 8061 models – Battery management during configuration in case it runs out – Alignment IP address with new default server – English translation correction – Time zone correction
1.10	05/11/2018	– First release